


Kam Tin & Pat Heung South



Lin Fa Tei
Archaeological Site

FIGURE 60
LIN FA TEI ARCHAEOLOGICAL SITE VS ALIGNMENT




FIGURE 61
PAT HEUNG SHEUNG TSUEN ARCHAEOLOGICAL SITE




FIGURE 62
YUEN LENG ARCHAEOLOGICAL SITE

Sheung Shui




FIGURE 63

MUK WU NGA YIU KILNS ARCHAEOLOGICAL SITE VS ALIGNMENT

Agreement No. CE 10/ 2008 (WS)

Agreement Title
REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION




FIGURE 64
HUNG LENG ARCHAEOLOGICAL SITE

Agreement No.

CE 10/ 2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
 OF WATER MAINS STAGE 4
 MAINS IN NEW TERRITORIES -
 INVESTIGATION, DESIGN AND CONSTRUCTION





FIGURE 65
SHA TAU KOK SHEK KIU TAU ARCHAEOLOGICAL SITE



Agreement No. CE 10/ 2008 (WS)

Agreement Title
REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION

FIGURE 66
POK TAU HA OLD LIME KILN

水務署
Water Supplies
Department

BLACK & VEATCH
Building a world of difference.





FIGURE 67
SHA TAU KOK SAN TSUEN ARCHAEOLOGICAL SITE



水務署
Water Supplies
Department



BLACK & VEATCH
Building a world of difference.

FIGURE 68a
AERIAL PHOTOGRAPH TAKEN IN
1964 SHOWING THE GENERAL
AREA OF TSEUNG KWAN O
SOUTH STUDY AREA

Agreement No.
CE 10/ 2008 (WS)

Agreement Title
REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION




FIGURE 68b
GEOLOGICAL MAP SHOWING THE
LOCATION OF THE FORMER AP
TSAI WAN IN HANG HAU AREA




FIGURE 69
1937 MAP SHOWING THE STUDY AREA OF
TSEUNG KWAN O NORTH STUDY AREA

水務署
 Water Supplies
 Department

BLACK & VEATCH
 Building a world of difference.

Agreement No.

CE 10/ 2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
 OF WATER MAINS STAGE 4
 MAINS IN NEW TERRITORIES -
 INVESTIGATION, DESIGN AND CONSTRUCTION



水務署
Water Supplies
Department



BLACK & VEATCH
Building a world of difference.

FIGURE 70
AERIAL PHOTOGRAPH TAKEN IN
2007 SHOWING THE GENERAL
AREA OF SAI KUNG STUDY AREA

Agreement No.

CE 10/ 2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION




FIGURE 71
GEOLOGICAL MAP SHOWING THE MA ON SHAN STUDY AREA





FIGURE 72
AERIAL PHOTOGRAPH TAKEN IN 1979 SHOWING
THE STUDY AREA OF TAI PO EAST



水務署
Water Supplies
Department




BLACK & VEATCH
Building a world of difference.

FIGURE 73
AERIAL PHOTOGRAPH TAKEN IN
1949 SHOWING THE EASTERN
PART OF THE TAI PO WEST

Agreement No.
CE 10/ 2008 (WS)

Agreement Title
REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION



水務署
Water Supplies
Department



BLACK & VEATCH
Building a world of difference.

FIGURE 74
AERIAL PHOTOGRAPH TAKEN IN
1991 SHOWING THE WESTERN
PART OF THE TAI PO WEST
STUDY AREA

Agreement No.
CE 10/ 2008 (WS)

Agreement Title
REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION





FIGURE 75

AERIAL PHOTOGRAPH TAKEN IN 1963 SHOWING
THE GENERAL VIEW OF THE FO TAN & MA LIU SHUI STUDY AREA



水務署
Water Supplies
Department



BLACK & VEATCH
Building a world of difference®

FIGURE 76
AERIAL PHOTOGRAPH TAKEN IN
1963 SHOWING THE STUDY AREA
OF SHA TIN

Agreement No.

CE 10/ 2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION




FIGURE 77

**AERIAL PHOTOGRAPH TAKEN IN 1964 SHOWING
THE STUDY AREA OF TAI WAI**



水務署
Water Supplies
Department



BLACK & VEATCH
Building a world of difference.

FIGURE 78
1939-40 MAP SHOWING THE
STUDY AREAS OF KWAI CHUNG
AND TSUEN WAN BEFORE
RECLAMATION

Agreement No. CE 10/ 2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION




FIGURE 79
1929-45 MAP SHOWING THE STUDY AREA OF SIU LAM



水務署
Water Supplies
Department



BLACK & VEATCH
Building a world of difference.


FIGURE 80
AERIAL PHOTOGRAPH TAKEN IN
1964 SHOWING THE STUDY AREA
OF TUEN MUN SOUTH AND
BUTTERFLY BEACH

Agreement No.

CE 10/ 2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION



水務署
Water Supplies
Department



BLACK & VEATCH
Building a world of difference.

FIGURE 81a
AREAS LOCATED WITHIN THE BOUNDARY
OF LUNG KWU TAN ARCHAEOLOGICAL
SITE REQUIRING ARCHAEOLOGICAL
WATCHING BRIEF AT LUNG TSAI

Agreement No.

CE 10/ 2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION OF
WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION





FIGURE 81c

**AREAS LOCATED WITHIN THE BOUNDARY OF LUNG KWU TAN
ARCHAEOLOGICAL SITE REQUIRING ARCHAEOLOGICAL WATCHING
BRIEF AT PAK LONG AND NAM LONG**

Agreement No. CE 10/ 2008 (WS)

Agreement Title
REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION



水務署
Water Supplies
Department



BLACK & VEATCH
Building a world of difference.


FIGURE 82
AREAS LOCATED WITHIN THE
BOUNDARY OF FU TEI HA
ARCHAEOLOGICAL SITE REQUIRING
ARCHAEOLOGICAL WATCHING BRIEF

Agreement No.

CE 10/2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION







FIGURE 83b

PROPOSED RE-ALIGNMENT OF WATER MAINS TO AVOID DIRECT IMPACT TO KILN IDENTIFIED DURING LATE MING




FIGURE 84a

AREAS LOCATED WITHIN THE BOUNDARY OF KEI LUN WAI

ARCHAEOLOGICAL SITE AT KEI LUN WAI STUDY AREA REQUIRING

ARCHAEOLOGICAL WATCHING BRIEF




FIGURE 84b

AREAS LOCATED WITHIN THE BOUNDARY OF SIU HANG TSUEN

ARCHAEOLOGICAL SITE AT SIU HANG TSUEN AND PO TONG HA STUDY

AREA REQUIRING ARCHAEOLOGICAL WATCHING BRIEF




FIGURE 84c
AREAS LOCATED WITHIN THE BOUNDARY OF SIU HANG TSUEN
ARCHAEOLOGICAL SITE AT SIU HANG TSUEN AND PO TONG HA STUDY
AREA REQUIRING ARCHAEOLOGICAL WATCHING BRIEF




FIGURE 84d
AREAS LOCATED WITHIN THE BOUNDARY OF KEI LUN WAI
ARCHAEOLOGICAL SITE AT TSZ TIN TSUEN REQUIRING
ARCHAEOLOGICAL WATCHING BRIEF




FIGURE 84e


**AREAS LOCATED WITHIN THE BOUNDARY OF SAN HING TSUEN
ARCHAEOLOGICAL SITE AT SAN HING TSUEN STUDY AREA REQUIRING
ARCHAEOLOGICAL WATCHING BRIEF**

Agreement No.

CE 10/ 2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION



Agreement No.

CE 10/ 2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION

FIGURE 84f **AREAS LOCATED WITHIN THE BOUNDARY OF SAN HING TSUEN** **ARCHAEOLOGICAL SITE AT SAN HING TSUEN STUDY AREA REQUIRING** **ARCHAEOLOGICAL WATCHING BRIEF**



FIGURE 85
1898 MAP SHOWING THE FORMER COASTLINE OF DEEP BAY IN YUEN
LONG AND PING SHAN STUDY AREAS



FIGURE 86

**AERIAL PHOTOGRAPH TAKEN IN 2009 SHOWING THE SITE FORMATION
WORK IN THE STUDY AREA OF KWU TUNG SOUTH (GOOGLE EARTH 2009)**

Agreement No.

CE 10/2008 (WS)

Agreement Title

REPLACEMENT AND REHABILITATION
OF WATER MAINS STAGE 4
MAINS IN NEW TERRITORIES -
INVESTIGATION, DESIGN AND CONSTRUCTION




FIGURE 87

GEOLOGICAL MAP SHOWING THE STUDY AREA OF SHA TAU KOK




FIGURE 88a
AREAS LOCATED AT MAN UK PIN REQUIRING ARCHAEOLOGICAL
WATCHING BRIEF




FIGURE 88b
AREAS LOCATED AT SHEUNG WO HANG REQUIRING ARCHAEOLOGICAL
WATCHING BRIEF




FIGURE 88c
AREAS LOCATED AT WO TONG KONG REQUIRING ARCHAEOLOGICAL
WATCHING BRIEF




FIGURE 88d
AREAS LOCATED AT LAP WO TSUEN REQUIRING ARCHAEOLOGICAL
WATCHING BRIEF




FIGURE 88e
AREAS LOCATED AT SAN TSUEN REQUIRING ARCHAEOLOGICAL
WATCHING BRIEF




FIGURE 88f
AREAS LOCATED AT TAM SHUI HANG REQUIRING ARCHAEOLOGICAL
WATCHING BRIEF

Appendix III

Condition Surveys

Appendix III - Condition Survey

The condition survey must be carried out by an approved qualified building surveyor who is a member of the Hong Kong Institution of Surveyors in the Building Surveying division or equivalent and an approved qualified engineer who is a member of the Hong Kong Institution of Engineers in the Civil or Structural Division or equivalent. The condition survey should also make reference (if appropriate) to the Practice Notes No. 289 issued by the Buildings Department of the Hong Kong SAR Government.

The condition survey report for all resources should contain the following;

- An appraisal of the state of the existing historic building and structures including location and condition of all cracks (including suitably referenced and catalogued photographs);
- An appraisal of their various types of construction, including foundations;
- The likely effect that the contractors method of working would have on the existing historic buildings and structures (including the structural stability of the structure;
- Setting of a safe limit for vibration levels for each historic structure (if required)
- Recommendations of any other protective measures to be taken during the construction and/ or operational phases (if required).

Vibration monitoring should be undertaken during the construction works to ensure that safe levels of vibration are not exceeded. The condition survey report must include a maximum acceptable ppv level for each of the resources. A monitoring schedule should be included in the condition survey report (including frequency for reading of monitoring equipment). The location of any monitoring equipment in the buildings must be submitted to AMO for review and approved by the owner before installation.

Monitoring measures and protective measures as stated in the condition survey report must be implemented by the contractor. The results of the monitoring must be submitted to the Engineer's Representatives within two days of each monitoring undertaken. If significant effects are identified to any of the monitored items the AMO should be informed. If the monitoring measurements exceed the safe limits set in the condition survey for any of the monitored structures, the Contractor shall take immediate corrective action as necessary, to bring peak particle velocity (PPV) levels within compliance.

Buffer Zone

- Buffer zones (to be marked out by temporary fencing) should be provided.